This Page Is Inserted by IFW Operations and is not a part of the Official Record

BEST AVAILABLE IMAGES


Defective images within this document are accurate representations of the original documents submitted by the applicant.


Defects in the images may include (but are not limited to):


- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS


IMAGES ARE BEST AVAILABLE COPY.


As rescanning documents will not correct images, please do not report the images to the Image Problem Mailbox.























MOT 120 dBA 135 dBA UL 125 dBA 140 dBA MOT 120 dBA 135 dBA UL 125 dBA 140 dBA RMS Peak Exceeds Spec. Condition Normal Meets Spec. Fault 120.5 dBA 131.5 dBA RMS Peak 107 dBA 117.5 dBA RMS* 人 (AND) Main Port Dia. High-Tol. Back Vol. Leak Port In Bezel High-Tol. (0.3mm) Main Port Dia. High-Tol in Audio Cover (1.5mm) 117.0 dBA 124.5 dBA 113.0 dBA 124.0 dBA 110.0 dBA 120.5 dBA in Bezel (1.5mm) Peak Unsnapped Bezel Unsnapped Bezel Peak Peak (Top Right) (Top Left) RMS RMS RMS Fault Effect Acoustic Shock Scorpion FSD Low Audio 132.1 dBA **Prob.** > MOT 99.99647% 0.001% **Prob.** > UL 0.00000% 0.00000% Peak 121.6 dBA RMS Voice at Prob. > UL Max. Level

Acoustic Output

Failure

Quantitative Results